

10/04/05, 054

WEST Search History

DATE: Saturday, January 14, 2006

<u>Hide?</u>	<u>Set Name</u>	<u>Query</u>	<u>Hit Count</u>
		<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L63	L62 and @pd > 20050805	8
<input type="checkbox"/>	L62	L61 or L60	348
<input type="checkbox"/>	L61	L48 not L60	87
<input type="checkbox"/>	L60	L59 or L45	261
<input type="checkbox"/>	L59	L58 not L45	205
<input type="checkbox"/>	L58	corrosion and L57	225
<input type="checkbox"/>	L57	L48 or L56	401
<input type="checkbox"/>	L56	L46 and ((zn or zinc) adj5 (coating or film or layer))	274
<input type="checkbox"/>	L55	(heat or baking or baked or heated or heating) and L53	346
<input type="checkbox"/>	L54	(heat or baking or baked or heated) and L53	341
<input type="checkbox"/>	L53	L48 or L52	374
<input type="checkbox"/>	L52	L51 not L45	221
<input type="checkbox"/>	L51	L49 and L50	228
<input type="checkbox"/>	L50	L46 and silane	638
<input type="checkbox"/>	L49	L46 and corrosion	921
<input type="checkbox"/>	L48	L47 not L45	170
<input type="checkbox"/>	L47	L41 and L46	188
<input type="checkbox"/>	L46	((((zn or zinc) and paste and flake) or "zinc flake" or "zinc alloy flake" or "zn flake" or "zn alloy flake") and (coating or film or layer))	3311
<input type="checkbox"/>	L45	L44 or L42	56
<input type="checkbox"/>	L44	L43 not L42	26
<input type="checkbox"/>	L43	((((zn or zinc) and paste and flake) or "zinc flake" or "zinc alloy flake" or "zn flake" or "zn alloy flake") and (coating or film or layer)).clm.	56
<input type="checkbox"/>	L42	(("zinc flake" or "zinc alloy flake" or "zn flake" or "zn alloy flake") and (coating or film or layer)).clm. (106/1.17 or 106/14.05 or 106/14.39 or 106/403 or 428/401 or 428/389 or 428/397 or 428/381 or 428/583 or 428/659 or 427/123 or 427/372.2 or 427/375 or 427/376.6 or 427/376.7 or 427/376.8 or 427/383.1 or 427/383.7 or 427/384 or 427/388.1 or 427/404 or 427/405 or 427/406 or 427/430.1 or 427/435 or 427/436)![CCLS]	30
		<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L40	L39 not L38	10

<input type="checkbox"/> L39	("zn flake" or "zn alloy flake") and (coating or film or layer)	13
<input type="checkbox"/> L38	("zinc flake" or "zinc alloy flake") and (coating or film or layer) <i>DB=PGPB,USPT,EPAB,JPAB; PLUR=YES; OP=OR</i>	33
<input type="checkbox"/> L37	L36 and @pd > 20050412	20
<input type="checkbox"/> L36	L35 and @pd>20041026	38
<input type="checkbox"/> L35	L33 or L22 or L17 or L19	336
<input type="checkbox"/> L34	L33 and @pd>20041026	26
<input type="checkbox"/> L33	L28 or L29 or L30 or L31	168
<input type="checkbox"/> L32	L31 and @pd > 20041026	11
<input type="checkbox"/> L31	L30 and @pd > 20040708	14
<input type="checkbox"/> L30	L27 not L28	56
<input type="checkbox"/> L29	L27 notL28	112
<input type="checkbox"/> L28	L25 or L26	112
<input type="checkbox"/> L27	((zinc adj2 alloy) and (zinc adj3 flake))	112
<input type="checkbox"/> L26	"zinc alloy flake"	15
<input type="checkbox"/> L25	(zinc adj3 flake) and paste	107
<input type="checkbox"/> L24	stapa 4znaL7	120
	<i>DB=USPT,PGPB,JPAB,EPAB; PLUR=YES; OP=OR</i>	
<input type="checkbox"/> L23	L22 and @pd > 20040105	2
<input type="checkbox"/> L22	L19 or L21	27
<input type="checkbox"/> L21	L20 not L17	3
<input type="checkbox"/> L20	((zinc or zn) adj4 alloy) and ((zinc or zn) adj4 flake)	140
<input type="checkbox"/> L19	L18 not L17	24
<input type="checkbox"/> L18	(zinc adj4 pulver\$) and (cure or cured or curing)	33
<input type="checkbox"/> L17	L15 or L16	286
<input type="checkbox"/> L16	L14 not L15	77
<input type="checkbox"/> L15	L10 or L11	209
<input type="checkbox"/> L14	(zinc adj4 flake) and (cure or cured or curing)	198
<input type="checkbox"/> L13	L11 not L12	68
<input type="checkbox"/> L12	(cure or curing or cured) and L11	23
<input type="checkbox"/> L11	L9 not L10	91
<input type="checkbox"/> L10	L3 or L5 or L6 or L7 or L8	118
<input type="checkbox"/> L9	(zinc adj4 alloy) and (zinc adj4 flake)	135
<input type="checkbox"/> L8	"zinc alloy flake"	15
<input type="checkbox"/> L7	L6 not L3	5
<input type="checkbox"/> L6	("lamellar zinc") and (cured or curing)	10
<input type="checkbox"/> L5	4026710[uref]	7
<input type="checkbox"/> L4	4620873[uref]	0

<input type="checkbox"/>	L3	("zinc alloy flake" or "zinc flake") and (cured or curing)	97
<input type="checkbox"/>	L2	("zinc alloy flak" or "zinc flake") and (cured or curing)	95
<input type="checkbox"/>	L1	((428/401 428/389 428/397 428/381)!.CCLS. (106/1.17 106/14.05 106/14.39 106/403)!.CCLS. (or/)!.CCLS.)	4060

END OF SEARCH HISTORY